1st and final Bill

M. A. R. 57 (Rule 116)
Measurement Book

No. B

Serial No. Construction of compound wall, Enter loose tiles to Endoor canteen 567355
Name of Work ... in Ward No. 14 ..... From ..... To .....
Name of Contractor of nature of Agency ..... Sri. Ramareddy .....
Date of commencement of work .....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Estimated cost: 4.80 lakhs Job code:- 044-18-000347 A.S. No: EE/DD/AS/08/2017-CS dt. 12/06/2017 T.S. No: EE/DD/TS/08/2017-CS dt. 01/04/2017 NOD : EE/DD/LOA/ /2017-CS dt. 05/07/2017						
(1)	Earthwork excavation by manual means in ordinary soil involving an average horizontal throw upto 2m and an average lift upto 1.5m excavated surface levelled and sides neatly dressed, the disposed earth to be levelled neatly afte						

Sd/- a.r
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿ
ಬಿ ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬೆಂಗಳೂರು

Scanned by CamScanner

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
1	2	Number 3	Length 4	Breadth 5	Depth 6	7	
	Excavating of clods complete as per specifications. As per premeasurement Qty recorded in this MB at Pg No. 587389 vide item No (1) @ Rate ₹ 150/cum					52.15 cum = ₹ 9387/-	
(38)	Providing and Constructing granular sub base with Size stone masonry in foundation with cm 1:6 and above mixed thickness as compact not less than 20 cm thick, bond stones at 3m. apart in each courses including cost of materials, labour, curing complete As per premeasurement Qty recorded in this MB at Pg No. 587389 vide item No (2) @ Rate ₹ 4400/cum					61.76 cum = 271744/-	

M. A. R. 57 (Rule 116)
Measurement Book
No. B

567356

Material No. .....
Name of Work ..... From..... To.....
Name of Contractor of nature of Agency .....
Date of commencement of work .....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	2	Number 3	Length 4	Breadth 5	Depth 6	7	8
(39)	Providing ruled pointing to coursed stone masonry with cm 1:3, 20mm deep, after roughing joints to depth of 20mm nicely trained including cost of materials, labour, curing complete as per specifications As per Premeasurement Qty recorded in this MB at Pg. No. 587390 vide item No (3) @ Rate ₹ 100/sqm					91.50 sqm = ₹ 9150/-	
(40)	Providing and constructing precast concrete Solid blocks with compressive strength not less than 40 Newton per sqm with Cm 1:4, masonary with Solid blocks						

Scanned by CamScanner

MEASUREMENT BOOK

Full description, etc, of work	Dimensions				Contents	*Reference to last Measurement
2	Number 3	Length 4	Breadth 5	Depth 6	7	
@ Rate 400 x 150 x 200 cm conforming to IS 2185/1979 in Superstructure including cost of materials, labour charges, scaffolding complete As per premeasurement Bk recorded in this MB at pg no. 587390/2 vide sl. no. (4) @ Rate ₹ 960/ Sqm					109.80 Sqm = 105408/-	
(5) Providing 20mm thick cement plaster in single coat with cement mortar 1:6 to stone masonry and concrete surface including rounding off corners wherever required Smooth rendering. As per premeasurement Bk recorded in this MB at pg no. 587391 vide sl. no. (5) @ @ Rate ₹ 270/ Sqm					219.60 Sqm = ₹ 59292/-	

M. A. R. 57 (Rule 116)
Measurement Book

No. B

567357

Serial No. .....

Name of Work ..... From..... To.....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
	2	Number 3	Length 4	Breadth 5	Depth 6	7	8
(6)	providing and laying in position PCC 1:2:4 with cement @ 240 kgs/cum with 20mm and down size graded granite metal CA @ 0.69 cum and FA @ 0.459 cum, machine mixed, concrete laid in layers not exceeding 150mm thick, well compacted for copings including cost of all materials, tools & machinery As per premeasurement Bk recorded in this MB at pg no. 587390/2 vide (6). @ Rate ₹ 860/ cum					3.65 cum = ₹ 3204/-	
					Total Bill Amount		= ₹ 475421/-

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents
		Number	Length	Breadth	Depth	
1	2	3	4	5	6	7
	Certificate ① The work is completed by contractor satisfactorily ② The contractor has removed all debris from worksport ③ There is no departmental issues made by contractor Sk d-ayar ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಜಿ ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ ಬೆಂಗಳೂರು					

Scanned by CamScanner